

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Errors
1	BRS	L1	2312	382/141,143-153.ccls.	USPAT; US-PGPUB	2004/06/16 07:45		0
2	BRS	L2	918	348/86-92,125,127.ccls.	USPAT; US-PGPUB	2004/06/16 07:45		0
3	BRS	L3	989	356/237.1,239.1.ccls.	USPAT; US-PGPUB	2004/06/16 07:45		0
4	BRS	L4	3830	1 2 3	USPAT; US-PGPUB	2004/06/16 07:45		0
5	BRS	L5	167	inspect\$ near composite	USPAT; US-PGPUB	2004/06/16 08:07		0
6	BRS	L6	23	5359525.URPN.	USPAT	2004/06/16 08:03		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	C o m m e n t s	E r r o r s	E r r o r s
1	BRS	L1	13095 2	(composite near (structure material))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/15 15:42			0
2	BRS	L2	229	1 near (inspect\$ detect\$ defect)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/15 15:46			0
3	BRS	L3	3544	1 same (inspect\$ detect\$ defect)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/15 15:45			0
4	BRS	L4	2693	1 same (inspect\$ detect\$ defect)	USPAT; US-PGPUB	2004/06/15 15:45			0
5	BRS	L5	74	3 and ((two multiple plural\$4) near light)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/06/15 15:47			0